

STONIMAGE

How to be A Global Leader in Services?

Many of us are facing after-sales trouble no matter private or governmental control company, time is invaluable and most worrying for us. Once the machine shut down, the production shut down either, and we start to lose money quickly and come to an operation crisis So what we do here?

- ◆ Fast Action in Services
- ◆ Unconditional Parts Supply
- ◆ Strong Professionalism

XINXIANG STONIMAGE TECHNOLOGY CO. LTD
新乡市石像科技有限公司

Tel: +86 373 5853611 +86 173 3736 9213

www.stonimagelift.com

Add: 1522#, Gongyuanlu, Hongqi district, Xinxiang city, Henan, China

STONIMAGE

was founded at end of 2014, is a global brand and manufacturer of lifting equipment and material handling equipment, we owns the most professional engineering team, R & D center and manufacturing base with rich experience in lifting industry. We are working with full passion in continuous innovation and improving services level.

Currently, STONIMAGE is focusing on Innovation, Manufacturing and Supplying of various lifting equipment, transportation machinery and construction machinery, mainly as below:

- Ladder Lift, Solar Panel Lift, Glass and window lift, Glass trolley
- Cargo truck elevator, Fish elevator, Mountain cargo Lift
- Electric scaffold, Wall building platform
- Electric forklift, Brick stacker, Installation Forklift for Pipe/Panel
- Scissor lift, Retractable stairs, Roller Shutter door lift
- Restaurant Meal elevator
- Ladder Scaffold
- Boat Lifter
- **Portable small forklift**



Portable small forklift
✓ For lifting goods.

Portable small forklift

- ✓ Max. Lifting Capacity: 300kg
- ✓ Lifting height: 1.2/ 1.6m
- ✓ For Lifting packages, materials, and others



Technical Data

Max. Lifting Capacity (kg)	Max. lifting height (m)	Battery	Dead weight	Self height (m)	Packing size (m)
300	1.2	12V/20AH	65kg	1.15	1.35*0.7*0.5
300	1.6	12V/20AH	70kg	1.25	1.5*0.7*0.5



Operation Notes:

- ◇ The Portable small forklift has been inspected and tested before leaving the factory, just need to connect the power supply when using.
- ◇ Check the electrical system, no penetration or exposure before use.
- ◇ Do no load operation for 1~3 times, then lifting with load.
- ◇ Keep the weight of work centered on the fork.
- ◇ No partial load, no overload, no climbing.
- ◇ People don't stand under the forklift.
- ◇ Stand on hard ground, not steep slopes.
- ◇ Don't use in bad weather
- ◇ A dedicated charger must be used, otherwise the battery will be damaged.



More pictures

更多图片



Product Description

Learn more and meet your various needs

